

Option 1: Quick Fill From Tap

Step 1. Leave lid on, fill bowl through central funnel.

Step 2. When filled tilt bowl at 45 degrees to allow air to escape through funnel. Finally, refer to step 2 in Option 2.





Option 2: Quick Fill From Hose Pipe

Step 1. Leave lid on, turn bowl upside down and direct hose up over central funnel to fill sides.



Step 2. Very quickly flip bowl back to the normal upright position. Water level in funnel should be approx. 20mm in depth.



Option 3: Easy Fill

Steps 1 & 2: Remove lid from base of the bowl and fill with water. Place lid back on the bowl.



Steps 3 & 4: Secure Lid and base together. Very quickly flip bowl upside down and then back to the normal upright position. Water level in funnel should be approx. 20mm in depth.

